



Three Phase Synchronous Machine

Synchronous machine is an **a. c.** machine

- Three forms
1. Synchronous Motor
 2. Syn Generator or Alternator
 3. Syn Condenser


Main Two windings: **1. Armature winding**

a) Similar to stator wdg of Ind. m/c.

b) Distributed ac winding.

c) Absorbs or imports ac power- **Motor**

d) Delivers or exports ac power - **Generator**




2. Field winding

- a) Similar to field wdg of dc machine
- b) Concentrated dc winding.
- c) Always absorbs or imports dc power
whether Motor or Generator

Therefore, syn. m/c is a **DOUBLY** excited ac m/c.

Armature winding is connected to **ac source**.


Field winding is connected to **dc source**.



Third winding: Damper or ammortisseur winding

- a) Similar to compensated winding of dc machine, housed in the pole shoe.
- b) But short circuited similar to squirrel cage wdg
- c) Damps the rotor oscillations.

Rotor material: Chromium-Nickel –Molybdenum steel=High tensile strength.



Construction


Two types:

1. **Salient pole** or **Projecting pole type** syn m/c

2. **Cylindrical rotor** or **Round rotor** or **Non-salient type** syn m/c

D-axis

$X_d = d$ -axis syn reactance



Q-axis


$X_q = q$ -axis syn reactance

Salient pole

Non-uniform air gap, $X_d \neq X_q$


D-axis

Uniform air gap
 $X_d = X_q$




Q-axis

Cylindrical rotor




Construction




There are two types of cylindrical rotor

1. Parallel slot rotor



Pole (1/3 without slot)






Construction

2. Radial slot rotor





Radial sided slots




Construction

2. Radial slot rotor



Radial sided slots




Construction

1. **Salient pole** syn m/c


2. **Cylindrical rotor** syn m/c

The Differences are:


1.



Salient pole




Cylindrical rotor



Construction

2. Non-uniform air gap	Uniform air gap
3. X_d d-axis syn reactance $\neq X_q$ q-axis syn reactance	$X_d = X_q = X_s$
4. Poles > 4	Poles ≤ 4
5. Used in LOW speed m/c	HIGH speed machine
6. Small core length, large diameter to accommodate large no of poles.	Long length, small diameter to limit large centrifugal forces due to high speed.



7. Hydro-generator in which rotor is driven by Hydro-Turbine is designed with this pole.


8. Under fault, there are more chances of deformation of rotor due to non-uniform air gap.

9. Output waveform is not sinusoidal
(more harmonics)

Turbo-generator in which rotor is driven by Steam-Turbine.

Under fault, there are less chances of deformation of rotor due to uniform air gap.


Output waveform is more nearer to sine wave.



10. Output Power


$$P = \frac{E_f V_t}{X_d} \sin \delta + \frac{V_t^2}{2} \left(\frac{1}{X_q} - \frac{1}{X_d} \right) \sin 2\delta$$


=Electromagnetic Power
+ Reluctance Power




$$P = \frac{E_f V_t}{X_s} \sin \delta$$


=Electromagnetic Power






Usually **field** wdg is on **rotor** and **armature** wdg on **stator**






Usually **field** wdg is on **rotor** and **armature** wdg on **stator**




Flux is set up

If rotor is rotated by Prime Mover
or by Motor or by Turbine




Usually **field** wdg is on **rotor** and **armature** wdg on **stator**


Generator





Arm Voltages




If speed is zero, no arm voltage is induced.





If DC supply is turned OFF







If DC supply is turned OFF





With no flux, if rotor is rotated, no arm voltage is induced.



Now consider **armature** wdg is on **rotor** and **field** wdg on **stator**







DC supply is given to field wdg

Flux is set up


Rotate the arm
By prime mover



Armature
Voltage




Generator




DC supply is
given to
field wdg

Flux is
set up


Rotate the arm
By prime mover



Armature
Voltage





Generator






DC supply is
given to
field wdg

Flux is
set up


Rotate the arm
by prime mover








Now rotate the rotor



Now rotate the rotor



Armature wdg

+ - DC supply Given to

Field

R Y B N



Shaft


4 Slip rings

Field wdg

Arm Voltages

t





The **advantages** of providing the **field** winding on **rotor** and **armature** winding on **stator**:

1. Field on rotor requires **TWO** slip rings. **Armature on rotor requires FOUR slip rings. Less slip ring losses.**
2. It is economical. For example:


Rating of armature=200MVA, 11kV

$$\therefore \text{Line current} = \frac{200 \times 10^3}{\sqrt{3} \times 11} = 10,500 \text{ A}$$

For this current, slip rings should be larger in size and properly insulated from the shaft for 11kV.


Rating of field=1MW, 500V

$$\therefore \text{Field current} = \frac{1000}{0.5} = 2000 \text{ A}$$



Slip rings should be **smaller in size** and are insulated for 500V only.

3. Stationary armature can be **INSULATED** satisfactory for higher voltages, ie upto 33kV.
4. Stationary armature can be **COOLED** more efficiently upto 1000MW or above.
5. Low power field wdg gives **LIGHTER** rotor, so **LOW** torque is required to rotate the rotor .
6. Higher speed and more output are possible for a given dimensions.




Synchronous Motor


Starting:

If 3-phase supply is given to armature, a **rotating** magnetic field is produced.

The speed of this rotating field is synchronous speed, $N_s = 120f/P$.

The stator produces a two pole field, which is rotating in **clockwise** direction. If field winding is excited, **poles** are created on rotor as shown.





Synchronous Motor

Starting:

If 3-phase supply is given to armature, a **rotating** magnetic field is produced.


The speed of this rotating field is synchronous speed, $N_s = 120f/P$.


The stator produces a two pole field, which is rotating in **clockwise** direction. If field winding is excited, **poles** are created on rotor as shown.

The angle between stator and rotor field axes is δ , **torque angle**

$$T = (P/\omega)$$

The torque is proportional to **$\sin\delta$** .






Synchronous Motor


Starting:


The torque varies sinusoidally with time, it **reverses** during each half cycle.



Therefore, the **average torque** over a complete cycle is **ZERO**.

Hence, syn **motor**, on its own, has **NO NET** starting torque.








Another way: Consider the **instant** shown in Fig.

N pole of stator **repels** N pole of rotor, producing **anticlockwise torque**.

After half cycle, i. e. after $10 \text{ msec} = 1/2f$, for 50Hz supply, stator poles occupy new positions as shown in Fig.








Another way: S pole of stator attracts N pole of rotor, producing clockwise torque.

Thus rotor rotates anticlockwise at one instant and after 10msec rotor rotates clockwise direction.

Due to inertia, rotor does not move in one direction and rotor R remains standstill. Thus net starting torque is zero.

Hence, synchronous motor is not self starting







Three phase supply is given to **stator**.

Synchronously rotating magnetic field is produced.

Now **rotate the rotor** in the same direction with same speed or speed near to **syn speed**.

Then field wdg is **excited**.





Three phase supply is given to **stator**.

Synchronously rotating magnetic field is produced.

Now **rotate the rotor** in the same direction with same speed or speed near to **syn speed**.

Then field wdg is **excited**.


There is **magnetic locking** between stator and rotor magnetic field


With **relative speed zero**, **stator N** pole is locked with **rotor S** pole and

stator S pole is locked with **rotor N** pole.

Rotor will now experience a **torque**.

If **prime mover** of rotor is cut off, **rotor** will continue to rotate in the same direction, with same **syn speed**.







Thus rotor **always** rotates at synchronous speed.

Hence name of this motor is **synchronous motor**.

If the **load** is applied on the rotor, **rotor lags** behind the stator field by some angle.





Thus rotor **always** rotates at synchronous speed.


Hence name of this motor is **synchronous motor**.

If the **load** is applied on the rotor, **rotor lags** behind the stator field by some angle.

This angle is called as torque **angle / load angle or power angle δ** .

The **starting** methods are


1. Auxiliary motor starting
2. Starting by Damper Winding (SCIM)
3. SRIM starting with High Torque



1. Auxiliary motor starting

The auxiliary motor may be **ac motor** or **dc motor**.

It is **mechanically coupled** with synchronous motor.



The armature wdg of synchronous motor is **energized** from 3-phase supply.

AC or DC motor is started and run **near** to synchronous speed




Now **DC supply** is given to field wdg of synchronous motor.

Field poles get **locked** with armature poles.

Synchronous motor starts **running** as a motor at syn speed.

The auxiliary motor can now **disconnected** from the supply or **decoupled** from mechanical coupling.

2. Starting by damper winding (Squirrel cage Induction motor starting)





2. Starting by damper winding (Squirrel cage Induction motor starting)

In order to make the motor self starting, the **damper or amortisseur wdg** is embedded in slots in the rotor pole faces.

This wdg is **short-circuited** at both ends by end rings.

This damper winding is **similar to squirrel cage wdg** of 3-ph induction motor.





2. Starting by damper winding (Squirrel cage Induction motor starting)

In this case, the syn motor can be started by **star-delta starting, reactor starting or auto-transformer starting.**

When 3-phase supply is given to armature, a **rotating magnetic field** is established.

Damper wdg develop **induction motor torque.**


The rotor is **accelerated** and speed is near to synchronous speed.

Before starting the field wdg can be **short-circuited** with or without some resistance

With some resistance, **starting torque** will be more.


Now the field wdg is open circuited and is energized from a DC source, **stator and rotor poles** will lock together.


Then rotor will run at **synchronous speed.**



3. Slip Ring Induction Motor starting with High Starting Torque (Synchronous – Induction Motor)

First it is operated as **SRIM** and then **synchronous** motor, therefore, syn motor may be called as **Syn-duction motor**.





For load requiring **high starting torques**, this type of starting method is used.


Rotor is similar to **SRIM** or wound rotor induction motor.

At the time of starting **high resistance is inserted** in rotor circuit to develop high starting torque.

As speed increase, this resistance is gradually **reduced to zero** .

The rotor short circuit is **removed** and rotor wdg is switched over to **DC supply**.

Thus rotor poles are **created** and are **attracted** by stator poles and **synchronism** is achieved.



Excitation Systems


Field winding

Always absorbs or imports dc power
whether Motor or Generator operation.

Field winding is connected to **dc source**.

The excitation systems are:

1. DC exciter




1. DC Exciter


Field of Pilot Exciter

Field of main Exciter

Alternator Field



Alternator field on **rotor** is connected to armature of main exciter on **rotor** through **slip rings and brushes**.




1. DC Exciter

An old conventional method of exciting field winding.


Three machines


1. Pilot exciter: **DC shunt generator** feeding field wdg of main exciter
2. Main exciter: Separately Excited **DC generator** feeding field wdg of main alternator.
3. Main 3-phase **alternator**:

They are **mechanically** coupled and driven by same shaft.



2. Static Excitation





2. Static Excitation

No rotating type of exciter, no friction.


Initially field winding is excited by **battery bank** through slip rings and brushes.

After building up of voltage, the output voltage is **fed back** to field through transformer and rectifier.


Then battery bank is **disconnected**.


Use of reliable and high power **SCR** (silicon controlled rectifier) gives **fast response**.

If other generators are **in operation**, then there is **no need** of battery bank for new generator.



3. Brushless Excitation






3. Brushless Excitation

This method consists of:

1. Pilot exciter: **3-phase generator** with permanent magnet **field or poles on rotor** and 3-phase armature wdg on stator.
2. Main exciter: **3-phase generator** with field on stator and armature on rotor.
3. Main 3-phase **alternator**:

They are **mechanically** coupled and driven by same shaft.

4. Rectifiers: 1. **Thyristor** controlled bridge.
2. **Silicon diode** bridge, mounted on shaft.



3. Brushless Excitation

The output of **pilot exciter** is fed to **thyristor** controlled rectifier.

After rectification, **dc output** is given to stationary **field winding of main exciter**

3-phase output of main exciter is fed through **hollow shaft** to **diode rectifier** which is mounted on shaft.

The dc output of diode rectifier is given to the main alternator **field without brushes and slip rings.**

Since this scheme does not require any sliding contact and brushes, this is called as **brushless excitation.**

For large **500MW and above**, turbo-generator, dc current is up to **10kA or above**, this scheme is **used.**

References

- [Slideshare.com](https://www.slideshare.com)